

20 INCH LIGHT BAR HOOD MOUNTING BRACKETS

(2007-2018 WRANGLER JK)

INSTALLATION INSTRUCTIONS

CONTENTS

(1) LH Mounting Bracket
(1) RH Mounting Bracket
(4) Allen Bolts


TOOLS REQUIRED

T-50 Torx Socket
Ratchet



STEP 1

Remove (4) T-50 Torx bolts from the hood hinges.



STEP 2

Align the appropriate mounting bracket to the vehicle hood hinge. Secure the light bracket and hood hinge to the vehicle hood using the included Allen bolts.

Use the LED light bar hardware to secure the light bar to the brackets. Lighting sold separately.

Installation is now complete.