

LED LIGHT BAR WINDSHIELD MOUNT

(2007-2018 WRANGLER JK)

INSTALLATION INSTRUCTIONS

CONTENTS

- (1) LH Windshield Mount
- (1) RH Windshield Mount
- (1) LH Foam Pad
- (1) RH Foam Pad
- (10) M8x1.25 x 30mm Allen Bolts
- (10) M8 Plastic Washers

TOOLS REQUIRED

- T-40 Torx Socket
- 5mm Allen Key/Socket
- Ratchet
- Exterior Detailer
- Microfiber Cloth

STEP 1



Remove (5) T-40 Torx bolts from the windshield hinge covers.

STEP 2




Clean the designated area using exterior detailer and a microfiber cloth to clear any dirt and debris from the vehicle.



STEP 3

Adhere the provided foam pad to the backside of the light bar mounting bracket using the bolt holes as alignment indicators. Firmly press the foam pad in place once aligned.



STEP 4

Align the light bar bracket to the vehicle. Secure the light bar mount to the vehicle using (5) M8x1.25 x 30mm Allen bolts and (5) M8 plastic washers. Tighten evenly until secure.



STEP 5

Repeat steps 1-4 to the opposite side of the vehicle.

Mounting bracket installation is now complete.



**LIGHT BAR
INSTALLATION**

Use (1) flat washer and (1) lock washer on each side of the light bar bracket to ensure the light bar hardware will not damage the mounting bracket finish.

With use of 50" light bar, push each bracket slightly inward to allow hardware to reach light bar.