

# MAXIMUS-3



JL WRANGLER / JT GLADIATOR

Side-Shooter/Cube Light Brackets

## INSTALLATION GUIDES

PLEASE MAKE SURE YOU READ AND UNDERSTAND THE ENTIRE INSTALLATION GUIDE BEFORE YOU START. WE EXPECT YOU TO HAVE BASIC MECHANICAL ABILITIES TO PERFORM THIS INSTALLATION.

WE RECOMMEND THAT YOU SEPARATE AND IDENTIFY ALL THE PARTS AND HARDWARE KITS YOU RECEIVED WITH YOUR SHIPMENT BEFORE YOU PROCEED TO DISASSEMBLE YOUR JEEP.

### Component List:

Cube Light Brackets Set

### Qty

1

### Tools Required:

M10 Socket/Wrench



## INSTALLATION STEPS:

1. Using M10 wrench/socket, remove the 2 factory fender bolts pointed with arrows in the picture below.
2. Align your Maximus-3 Light Bracket to the holes and bolt down using the factory bolts as shown below.
3. Bolt your Lights to the bracket as shown and route the wiring under the bracket and under the hood as desired, then connect to your Auxiliary Accessories wiring or wire following wiring instructions supplied with your lights. Use cable tie loops to secure the wire to bracket.
4. Repeat on the other side.



Your installation is complete. If you have questions regarding this installation, please contact us at [sales@maximus-3.com](mailto:sales@maximus-3.com) or call 248 821 6654.